

AD-A106 168

PRC CONSOER TOWNSEND INC ST LOUIS MO
NATIONAL DAM SAFETY PROGRAM. B & K LAKE NUMBER 1 DAM (MO 30506)--ETC(U)
SEP 79 W G SHIFRIN
DACW43-79-C-0075

F/G 13/13

NL

UNCLASSIFIED

1 OF 2

AD-A106 168



h

h

h

h

h

h

h

h

h

h

h

h

h

h

h

h

h

h

h

h

h

h

h

h

h

h

h

AD A106168

①

MISSISSIPPI-KASKASKIA-ST. LOUIS BASIN

LEVEL II

B & K LAKE NO.1 DAM
WARREN COUNTY, MISSOURI
MO 30506

**DTIC
ELECTE
S D
OCT 27 1981
E**

**PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM**



**United States Army
Corps of Engineers**
...Serving the Army
...Serving the Nation

St. Louis District

PREPARED BY: U. S. ARMY ENGINEER DISTRICT, ST. LOUIS


FOR: STATE OF MISSOURI

This document has been approved
for public release and sale; its
distribution is unlimited.

SEPTEMBER, 1979

81 10 26 091

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)



SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)



DEPARTMENT OF THE ARMY
ST. LOUIS DISTRICT, CORPS OF ENGINEERS
210 NORTH 12TH STREET
ST. LOUIS, MISSOURI 63101

IN REPLY REFER TO

SUBJECT: B & K Lake No. 1 Dam (Mo. 30506) Phase I Inspection Report

This report presents the results of field inspection and evaluation of the B & K Lake No. 1 Dam (Mo. 30506).

It was prepared under the National Program of Inspection of Non-Federal Dams.

This dam has been classified as unsafe, non-emergency by the St. Louis District as a result of the application of the following criteria:

- 1) Spillway will not pass 50 percent of the Probable Maximum Flood
- 2) Overtopping could result in dam failure
- 3) Dam failure significantly increases the hazard to loss of life downstream

SUBMITTED BY:

SIGNED

Chief, Engineering Division

25 SEP 1979

Date

APPROVED BY:

SIGNED

Colonel, CE, District Engineer

25 SEP 1979

Date

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A	

B & K LAKE NO. 1 DAM
WARREN COUNTY, MISSOURI

MISSOURI INVENTORY NO. 30506

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

PREPARED BY
CONSOER, TOWNSEND AND ASSOCIATES LTD.
ST. LOUIS, MISSOURI
AND
ENGINEERING CONSULTANTS, INC.
ENGLEWOOD, COLORADO
A JOINT VENTURE

UNDER DIRECTION OF
ST. LOUIS DISTRICT, CORPS OF ENGINEERS
FOR
GOVERNOR OF MISSOURI

SEPTEMBER 1979

C

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam: B & K Lake No. 1 Dam, Missouri Inv. No. 30506
State Located: Missouri
County Located: Warren
Stream: An Unnamed Tributary of Lost Creek
Date of Inspection: May 19, 1979

Assessment of General Condition

B & K Lake No. 1 Dam was inspected using the "Recommended Guidelines for Safety Inspection of Dams". These guidelines were developed by the Chief of Engineers, U.S. Army, Washington, D.C., with the help of Federal and State agencies, professional engineering organizations, and private engineers. The resulting guidelines are considered to represent a consensus of the engineering profession.

→ Based on the criteria in the guidelines, the dam is in the high hazard potential classification, which means that loss of life and appreciable property loss could occur in the event of failure of the dam. Within the estimated five mile damage zone downstream of the dam are seven houses, six buildings, and one road crossing which may be subjected to flooding, with possible damage and/or destruction, and possible loss of life. B & K Lake No. 1 Dam is in the small size classification since it is less than 40 feet high and impounds less than 1,000 acre-feet of water.

Our inspection and evaluation indicates that the spillway of B & K Lake No. 1 Dam does not meet the criteria set forth in the guidelines for a dam having the above size and hazard potential. B & K Lake No. 1 Dam being a small size dam with a high hazard potential, is required by the guidelines to pass from one-half of the Probable Maximum Flood to the Probable Maximum Flood without overtopping. Since there is high hazard potential downstream of the dam, the appropriate spillway design flood for this dam is the Probable Maximum Flood. It was determined that the reservoir/spillway system can accommodate 17 percent of the Probable Maximum Flood without overtopping the dam. Our evaluation also indicates that the reservoir/spillway system can accommodate the 100-year flood without overtopping the dam.

The Probable Maximum Flood is defined as the flood discharge that may be expected from the most severe combination of critical meteorological and hydrologic conditions that are reasonably possible in the region. The 100-year flood is defined as a flood having one percent chance of being equalled or exceeded during any given year.


Other deficiencies noted by the inspection team were: the seepage on the downstream slope at the right abutment contact; sloughing and erosion on the upstream embankment slope; trees and brush in the spillway channel; a need for periodic inspection by a qualified engineer and a lack of maintenance schedule. The lack of stability and seepage analyses on record is also a deficiency that should be corrected.

It is recommended that the owner take action to correct
or control the deficiencies described above.

Walter G. Shifrin

Walter G. Shifrin, P.E.





Overview of B & K Lake No. 1 Dam

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

B & K LAKE NO. 1 DAM, MISSOURI INV. NO. 30506

TABLE OF CONTENTS

<u>Sect. No.</u>	<u>Title</u>	<u>Page</u>
SECTION 1	PROJECT INFORMATION	1
	1.1 General	1
	1.2 Description of Project	3
	1.3 Pertinent Data	9
SECTION 2	ENGINEERING DATA	12
	2.1 Design	12
	2.2 Construction	12
	2.3 Operation	12
	2.4 Evaluation	12
SECTION 3	VISUAL INSPECTION	14
	3.1 Findings	14
	3.2 Evaluation	18

TABLE OF CONTENTS

(Continued)

<u>Sect. No.</u>	<u>Title</u>	<u>Page</u>
SECTION 4	OPERATION PROCEDURES	19
	4.1 Procedures	19
	4.2 Maintenance of Dam	19
	4.3 Maintenance of Operating Facilities	20
	4.4 Description of Any Warning System in Effect	20
	4.5 Evaluation	20
SECTION 5	HYDRAULIC/HYDROLOGIC	21
	5.1 Evaluation of Features	21
SECTION 6	STRUCTURAL STABILITY.	26
	6.1 Evaluation of Structural Stability	26
SECTION 7	ASSESSMENT/REMEDIAL MEASURES	28
	7.1 Dam Assessment	28
	7.2 Remedial Measures	30

TABLE OF CONTENTS

(Continued)

LIST OF PLATES

	<u>Plate No.</u>
LOCATION MAP	1
PLAN AND ELEVATION OF DAM	2
GEOLOGIC MAPS	3-4
SEISMIC ZONE MAP	5

APPENDICES

APPENDIX A	-	PHOTOGRAPHS
APPENDIX B	-	HYDROLOGIC COMPUTATIONS

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

B & K Lake No. 1 Dam, Missouri Inv. No. 30506

SECTION 1: PROJECT INFORMATION

1.1 General

a. Authority

The Dam Inspection Act, Public Law 92-367 of August, 1972, authorizes the Secretary of the Army, through the Corps of Engineers, to initiate a national program of dam inspections. Inspection for B & K Lake No. 1 Dam was carried out under Contract DACW 43-79-C-0075 to the Department of the Army, St. Louis District, Corps of Engineers, by the engineering firms of Consoer, Townsend & Associates Ltd., and Engineering Consultants, Inc. (A Joint Venture), of St. Louis, Missouri.

b. Purpose of Inspection

The visual inspection of B & K Lake No. 1 Dam was made on May 19, 1979. The purpose of the inspection was to make a general assessment as to the structural integrity and operational adequacy of the dam embankment and its appurtenant structures.

c. Scope of Report

This report summarizes available pertinent data relating to the project; presents a summary of visual observations made during the field inspection; presents an assessment of hydrologic and hydraulic conditions at the site; presents an assessment as to the structural adequacy of the various project features; and assesses the general condition of the dam with respect to safety.

Subsurface investigations, laboratory testing, and detailed analyses were not within the scope of this study. The conclusions drawn herein, therefore, are based on the presence of, or absence of, obvious signs of distress. No warranty as to the absolute safety of the project features is implied by the conclusions presented in this report.

It should be noted that reference in this report to left or right abutments is as viewed looking downstream. Where left abutment or left side of the dam is used in this report, this also refers to east abutment or side, and right to the west abutment or side.

d. Evaluation Criteria

Criteria used to evaluate the dam were furnished by the Department of the Army, Office of the Chief of Engineers, in "Recommended Guidelines for Safety Inspection of Dams", Appendix D. These guidelines were developed with the help of several Federal agencies and many State agencies, professional engineering organizations, and private engineers.

1.2 Description of the Project

a. Description of Dam and Appurtenances

It should be noted that design drawings are not available for the dam or appurtenant structures. The following description is based on visual observations and information taken from Fenneman, N.M., "Physiographic of Eastern United States", 1946.

The dam is a compacted earthfill structure. The crest width is 14 feet, and the crest length is 475 feet. The crest elevation varies from 833.25 to 833.58 feet above MSL, and the maximum height of the embankment was measured as 28.0 feet.

The downstream slope of the embankment was measured to be 1V to 2H. It was not possible to accurately measure the upstream slope because of high reservoir level.

No riprap was placed on the upstream face. The entire exposed embankment has a grass cover.

There is a dam named as B & K Lake No. 2 Dam upstream of B & K Lake No. 1 Dam. The inventory number of the dam is Mo. 11002. The upstream dam has been taken into consideration in the hydrologic and hydraulic evaluation of B & K Lake No. 1 Dam.

The damsite is situated on the border between the Dissected Till Plain Section of Central Lowlands Physiographic Province which extends to the north and the Ozark Plateau Province to the south. Although the area in which the dam and reservoir are located was glaciated during Pleistocene time,

the till and loess which characterize the uplands of the Till Plains have been largely removed by erosion since the end of the Pleistocene. The area is characterized by wooded hills which have gentle to steep slopes.

The bedrock geology of the area, as shown on the Geologic Map of Missouri (1979), typically consists of gently northeastwardly dipping (ca. 30 - 50 feet/mile) sediments of Paleozoic age. North of Warren County these beds are often capped by young (Pleistocene) deposits of glacial drift and wind blown loess. In the southern areas of the county the bedrocks are generally covered by residual soil, colluvium, or alluvium. The rocks underlying the area are predominately carbonates (limestones and dolomites) although beds of sandstone and shale are not infrequent.

The bedrock of Warren County contains some minor folding. The largest known geologic structure in the area is a gentle anticline centered about 2 1/2 miles northwesterly of the town of Warrenton. This structure trends nearly north-south and is about 2 1/2 miles long. It is not known if this fold affects the attitude of the beds beneath the site.

The Soil Conservation Service reports (Soil Survey of Montgomery and Warren Counties, Missouri, 1978) that the soils in the bottom land at the damsite are clayey silt (ML) and cherty, clayey gravel (GC). The upslope soils consist largely of silty clay (CL-ML) and clay (CL).

The spillway for B & K Lake No. 1 Dam is an open channel depression located just beyond the right abutment of the dam. Approximately 50 feet downstream of the upstream edge of the spillway, which has a 12 inch high wire mesh trashscreen, a concrete weir has been constructed. This weir

is a 10 inch thick concrete wall with a total length of 54 feet. The weir is trapezoidal in shape, with a 16 foot bottom width, a side slope of 1V to 10.4H on the right bank and 1V to 20H on the left bank. Five 12-inch diameter corrugated metal pipes are constructed through the concrete weir, placed on 4 foot centers. The outside pipes have a total length of 6 feet, while the three inside pipes have a length of 4 feet. The elevation difference between the crest of the embankment and the crest of the concrete weir is 1 foot, 3 inches. The difference between the crest of the weir and the invert of the outside corrugated metal pipes is 1 foot, 4 inches, while the inside corrugated metal pipes are 8 inches lower than the outside pipes.

Discharges through the spillway pipe and over the weir flow through a channel adjacent to the right abutment contact to the downstream toe of the dam. The channel is an earth channel with rock riprap recently placed at the bottom and sides of the channel.

There is no low level drain pipe or outlet works for this dam.

b. Location

The dam is located at the headwaters of a small intermittent stream which is tributary to Lost Creek. The stream flows to the south about a quarter mile before entering Lost Creek.

Lost Creek flows southward from the confluence for about 2 miles and then southwesterly for about 11 miles where it flows into the Missouri River near the village of Gore just upstream of Mile 90. The upper reaches of Lost Creek are intermittent but, about 3 miles below the dam it becomes perennial.

The major access to the damsite from Warrenton, Missouri is west on the Interstate Highway No. 70 frontage road approximately 3 miles to a gravel road heading south, thence south on this road 1/4 mile to a private road to the east. The damsite is located at the end of the private road, approximately 1,000 feet from the beginning of the road. The dam and reservoir are shown in the Warrenton Quadrangle Sheet (7.5 minute series) in Section 24, Township 47 North, Range 3 West.

c. Size Classification

According to the "Recommended Guidelines for Safety Inspection of Dams", by the U.S. Department of the Army, Office of the Chief Engineer, the dam is classified in the dam size category as being "Small" since its storage is less than 1,000 acre-feet. The dam is also classified as "Small" in dam height category because its height is less than 40 feet. The overall size classification is, accordingly, "Small" in size.

d. Hazard Classification

The dam has been classified as having "High" hazard potential in the National Inventory of Dams, on the basis that in the event of failure of the dam or its appurtenances, excessive damage could occur to downstream property, together with the possibility of the loss of life. Our findings concur with the classification. Within the estimated five mile damage zone downstream of the dam are seven houses, six buildings, and one road crossing.

e. Ownership

The dam and lake are owned by B & K Construction Company. The mailing address is B & K Construction Company, c/o Ken Davis Sr., 4140 Cypress Road, St. Ann, Missouri, 63114.

f. Purpose of Dam

The purpose of the dam is to impound water for recreational use as a private lake.

g. Design and Construction History

B & K Lake No. 1 Dam was originally built in 1945 (est.) by Gene Rugh of Wright City, Missouri. Efforts to contact the original builder were futile and it is very doubtful if any formal design was done at the time of original construction.

The dam was rebuilt in 1977 by the present owner, Mr. Ken Davis of B & K Construction Company. Mr. Davis was his own engineer for the reconstruction and according to him, a 20 foot wide key trench was placed at the downstream toe. Also the crest width was increased from 6 feet to 14 feet. The owner informed the inspection team that the material for the reconstruction was taken from an area several hundred feet north of the left abutment.

h. Normal Operational Procedures

There are no specific operational procedures for the dam. The lake is used for recreational purposes and the water level below the spillway crest is controlled by rainfall, runoff and evaporation.

1.3 Pertinent Data *

a. Drainage Area (square miles):	0.25
b. Discharge at Damsite	
Estimated experienced maximum flood (cfs):	NA
Estimated ungated spillway capacity at maximum pool elevation (cfs):	125
c. Elevation (Feet above MSL)	
Top of dam:	833.25
Spillway crest:	
Service Spillway	830.0
Emergency Spillway	832.0
Normal Pool	830.0
Maximum Pool (PMF):	834.88
d. Reservoir	
Length of maximum pool:	1400 feet
e. Storage (Acre-Feet)	
Top of dam:	108
Spillway crest:	
Service Spillway	72
Emergency Spillway	92
Normal Pool:	72
Maximum Pool(PMF):	138

* Maximum pool referred to in this section indicates pool at top of dam elevation unless otherwise specified.

f. Reservoir Surface (Acres)

Top of dam:	13.2
Spillway crest:	
Service Spillway	9
Emergency Spillway	11.4
Normal Pool:	9.0
Maximum Pool(PMF):	15.5

g. Dam

Type:	Rolled Earthfill
Length:	475 feet
Structural Height:	28.0 feet
Hydraulic Height:	28.0 feet
Top width:	14.0 feet
Side slopes:	
Downstream	1V to 2H
Upstream	Unknown
Zoning:	Unknown
Impervious core:	Unknown

Cutoff:	Unknown
---------	---------

Grout curtain:	Unknown
----------------	---------

h. Diversion and Regulating Tunnel None

i. Spillway

Type:	
Service Spillway	5 - 1' diameter CMP, Uncontrolled
Emergency Spillway	Trapezoidal Concrete Weir, Uncontrolled
Length of weir:	

Service Spillway	5 - 1' diameter CMP
Emergency Spillway	16 feet
Crest Elevation (feet above MSL):	
Service Spillway	830 for 3 pipes and 830.67 for 2 pipes
Emergency Spillway	832

j. Regulating Outlets

None

SECTION 2 : ENGINEERING DATA

2.1 Design

Design drawings are not available for the dam for either the original construction or the modifications done in 1977.

2.2 Construction

No records or construction data is available for B & K Lake No. 1 Dam.

2.3 Operation

No operational data is available for the lake and dam because there is no specific operational procedure for this dam.

2.4 Evaluation

a. Availability

No design drawings, design computations, construction data, or operation data is available.

In addition, no pertinent data was available for review of hydrology, spillway capacity, flood routing through the reservoir, slope stability, seepage analysis, or foundation conditions.

b. Adequacy

The lack of engineering data did not allow for a definitive review and evaluation. Therefore, the adequacy of this dam could not be assessed from the standpoint of reviewing and evaluating design, operation and construction data, but is based primarily on visual inspection, past performance history, and sound engineering judgment.

Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency. These seepage and stability analyses should be performed for appropriate loading conditions (including earthquake loads) and made a matter of record.

c. Validity

No valid engineering data is available.

SECTION 3: VISUAL INSPECTION

3.1 Findings

a. General

A visual inspection of the B & K Lake No. 1 Dam was made on May 19, 1979. The following persons were present during the inspection:

<u>Name</u>	<u>Affiliation</u>	<u>Disciplines</u>
Dr. M. A. Samad	Engineering Consultants, Inc.	Project Engineer, Hydraulics and Hydrology
Jon Diebel	Engineering Consultants, Inc.	Structural and Mechanical
Peter Strauss	Engineering Consultants, Inc.	Soils
Peter Howard	Engineering Consultants, Inc.	Geology
Kevin Blume	Consoer, Townsend & Assoc., Ltd.	Civil and Structural

Specific observations are discussed below.

b. Dam

The crest and downstream slope of the dam has a heavy grass cover which appears to be adequately protecting the embankment materials against surface erosion. The upstream slope has no riprap protection and has consequently undergone erosion from wave action. Scarps ranging from 1-3 feet high have been cut into the upper part of the upstream face. No trees or bushes were observed on the dam slopes.

The dam, as seen from materials in the scarps, appears to be composed of residual soils with gravel.

Some seepage in the form of standing water was seen next to a large tree adjacent to the downstream toe near the left abutment. Damp conditions were noted next to the spillway channel in a row of trees and bushes about 20 feet downstream of the downstream toe of dam near the right abutment. Standing water was seen at about the same level in the spillway channel. Boggy conditions were also seen about 300 feet downstream of the toe of the embankment at the central part of the dam.

No signs of instability were seen on the embankment or in the foundation at any location.

The present owner reported that the original dam leaked in the right abutment-spillway area. He reported that in 1977 he cleared trees from the downstream face and placed 9000 cubic yards of clay against the downstream slope to stop seepage. A core trench about 20 feet wide and 14 feet high was constructed at the downstream toe of the embankment and

the crest width increased to 14 feet during the embankment construction.

There are no rock outcrops at the damsite. According to the Geologic Map of Missouri (1979) the covered bedrock is Burlington Limestone (Osagean Series, Mississippian). The Burlington is predominately cherty, crinoidal limestone.

The Soil Conservation Service reports (Soil Survey of Montgomery and Warren Counties, Missouri, 1978) that the soils in the bottom land at the site are clayey silt (ML) and cherty, clayey gravel (GC). The upslope soils consist largely of silty clay (CL-ML) and clay (CL).

It is not known if the dam rests on bedrock or not. If it does, the Burlington will form an adequate foundation provided it was blanketed with sufficient impervious material to prevent the possible development of solution channels along possible joints or joint intersections in the limestone.

The type of material used in the embankment fill is not known.

c. Appurtenant Structures

(1) Spillway

The spillway approach channel to the concrete weir is covered by a thin grass cover. The center of the channel is a small erosion gully. The concrete in the weir structure is old and deteriorated, but appears to be structurally sound. The corrugated metal pipes through the concrete weir are in satisfactory condition.

Upstream and downstream of the weir trees and large brush are growing in the channel. This vegetation will inhibit flows through the spillway channel. The spillway channel downstream of the weir has recently had rock riprap placed in the bottom of the channel from a point approximately 30 feet downstream of the weir to and beyond the toe of the embankment. The sides of the channel exhibit sloughing and erosion due to flows through the spillway channel.

The spillway channel is separated from the embankment by a small ridge of natural ground. This ridge is heavily vegetated with trees and brush, but substantial erosion is occurring on the bank of this channel.

(2) Outlet Works

There is no low level drain or outlet works at the damsite.

d. Reservoir Area

The water surface elevation was approximately 830 feet above MSL at the time of inspection.

The reservoir rim is gently sloping with trees and woods near the shore. No evidence of instability was observed.

e. Downstream Channel

The downstream channel is well defined with some vegetative and tree growth. The channel joins Lost Creek about 1/4 mile downstream from the dam. No major obstacles were found in the channel which would significantly reduce the

hydraulic efficiency of the channel. Some erosion could be observed in a few areas.

3.2 Evaluation

The following items were observed which could affect the safety of the dam, or which will require maintenance within a reasonable period of time.

1. Wave erosion on the upstream embankment slope.
2. Seepage observed downstream of the toe of the embankment at the left and right abutment of the dam.
3. Trees and large brush growing in several areas of the spillway discharge channel.
4. Erosion on the banks of the spillway discharge channel, particularly on the left bank adjacent to the dam embankment.

SECTION 4: OPERATIONAL PROCEDURES

4.1 Procedures

B & K Lake No. 1 Dam is used solely for recreational purposes. No provisions were made for drawing down the reservoir or regulating the water level. No formal operational procedures are in effect for this dam.

4.2 Maintenance of Dam

The dam is maintained by the owner Mr. Ken Davis and his caretaker, Mr. Bob Curtis who lives on the property. The dam seems to be maintained satisfactorily. the downstream and upstream slopes, along with the crest, seem to be kept free of saplings and bushes. Periodically the grasses are mowed on the dam. At the time of inspection it was apparent that the spillway channel had been recently lined with rocks ranging in size from 2 inches to 24 inches in diameter.

The approach channel to the spillway is somewhat blocked with trees and bushes. There is also a close-meshed trash rack at the entrance to the approach channel which is partially clogged with debris. These areas should receive attention within a reasonable period of time.

4.3 Maintenance of Operating Facilities

There are no operating facilities at the damsite which require maintenance. No water level records are kept for the lake.

4.4 Description of Any Warning System in Effect

The inspection team is not aware of any warning system in effect.

4.5 Evaluation

The operation and maintenance for B & K Lake No. 1 Dam, with the exception of the spillway approach channel, seems to be satisfactory. Also the upstream slope at the water level is showing signs of erosion.

No operation is required for the lake and dam, however, the items suggested for maintenance should receive attention within a reasonable length of time.

SECTION 5: HYDRAULIC/HYDROLOGIC

5.1 Evaluation of Features

a. Design

The watershed area of B & K Lake No. 1 Dam upstream from the dam axis consists of approximately 157 acres. There is a dam named as B & K Lake No. 2 Dam (Mo. 11002) upstream of B & K Lake No. 1 Dam. The watershed area between the upstream dam and B & K Lake No. 1 Dam investigated in this report is about 132 acres. Most of the watershed area is wooded and covered with grass. Land gradients in the watershed average roughly 4 percent. B & K Lake Dam No. 1 is located on an unnamed tributary of Lost Creek. The reservoir is about 1/4 mile upstream from the confluence of the unnamed tributary and Lost Creek. At its longest arm the watershed is approximately 0.6 mile long. A drainage map showing the watershed area is presented as Plate 1 in Appendix B.

Evaluation of the hydraulic and hydrologic features of B & K Lake No. 1 Dam was based on criteria set forth in the Corps of Engineers' "Recommended Guidelines for Safety Inspection of Dams", and additional guidance provided by the St. Louis District of the Corps of Engineers. The Probable Maximum Flood (PMF) was calculated from the Probable Maximum Precipitation (PMP) using the methods outlined in the U.S. Weather Bureau Publication, Hydrometeorological Report No. 33. The probable maximum storm duration was set at 24 hours, and storm rainfall distribution was based on criteria given in EM 1110-2-1411 (Standard Project Storm). The SCS method was used

for deriving the unit hydrographs, utilizing the Corps of Engineers' computer program HEC-1 (Dam Safety Version). Two unit hydrographs were derived. One unit hydrograph was for the drainage above the B & K Lake No. 2 Dam; another unit hydrograph was for drainage area between B & K Lake No. 2 Dam and B & K Lake No. 1 Dam. The parameters of the unit hydrographs are presented in Appendix B. The SCS method was used for determining loss rate. The hydrologic soil group of the watershed was determined by use of published soil maps. The hydrologic soil group of the watershed and the SCS curve number are also presented in Appendix B. The curve number, the unit hydrograph parameters, and the PMP rainfall were directly input to the HEC-1 (Dam Safety Version) computer program to obtain the PMF hydrograph. The computed peak discharges of the PMF and one-half of the PMF at the B & K Lake No. 2 Dam reservoir are 647 cfs and 324 cfs respectively. The peak discharges of the PMF and one-half of the PMF between B & K Lake No. 2 Dam and B & K Lake No. 1 Dam are 2,376 and 1,368 cfs respectively.

Both the PMF and one-half of the PMF inflow hydrographs at the B & K Lake No. 2 Dam were routed through B & K Lake No. 2 Dam reservoir by the Modified Puls Method, also utilizing the HEC-1 (Dam Safety Version) computer program. The peak outflow discharges for the PMF and one-half of the PMF at B & K Lake No. 2 Dam are 520 cfs and 193 cfs, respectively. Both the PMF and one-half of the PMF when routed through the reservoir resulted in overtopping of B & K Lake No. 2 Dam. The outflow hydrographs at B & K Lake No. 2 Dam were combined with the PMF and one-half of the PMF hydrographs for B & K Lake No. 1 Dam. The combined hydrographs for both the PMF and one-half of the PMF, were then routed through B & K Lake No. 1 Dam reservoir. The peak outflow discharges for the PMF and one-half of the PMF at B & K Lake No. 1 Dam are

2,626 cfs and 1,217 cfs respectively. Both the PMF and one-half of the PMF, when routed through the reservoir resulted in overtopping of the B & K Lake No. 1 Dam.

The stage-outflow relations for the spillways were prepared from field notes, and sketches, prepared during the field inspection. The reservoir stage-capacity data were based on the U.S.G.S. Warrenton Quadrangle topographic map (7.5 minute series). The spillway and overtop rating curves and the reservoir capacity curves for B & K Lake No. 1 & No. 2 Dams are presented as Plates 2 through 5 in Appendix B.

From the standpoint of dam safety, the hydrologic design of a dam aims at avoiding overtopping. Overtopping is especially dangerous for an earth dam because the downrush of waters over the crest can erode the dam embankment and release all the stored water into the downstream floodplain. The safe hydrologic design of a dam requires a spillway crest height that can handle a very large and exceedingly rare flood without overtopping.

The Corps of Engineers designs its dams to safely pass the Probable Maximum Flood that is estimated could be generated from the upstream watershed. This is the generally accepted criterion for major dams throughout the world, and is the standard for dam safety where overtopping would pose any threat to human life. According to the Corps criteria, the hydrologic requirement for safety for this dam is the capability to pass from one-half of the Probable Maximum Flood to the Probable Maximum Flood without overtopping.

b. Experience Data

It is believed that no records of reservoir stage or spillway discharge are maintained for this site.

c. Visual Observations

Observations made of the spillway during the visual inspection are discussed in Section 3.1c(1) and evaluated in Section 3.2.

d. Overtopping Potential

As indicated in Section 5.1-a, both the Probable Maximum Flood and one-half of the Probable Maximum Flood, when routed through the reservoir, resulted in overtopping of the dam. The peak outflow discharges for the PMF and one-half of the PMF at B & K Lake No. 1 Dam are 2,626 cfs and 1,217 cfs respectively. The PMF overtopped the dam crest by 1.63 feet and one-half of the PMF overtopped the dam crest by 0.91 feet. The total duration of embankment overflow is 6.67 hours during the PMF, and 4.83 hours during one-half of the PMF. The spillways for B & K Lake No. 1 Dam are capable of passing a flood equal to approximately 17 percent of the PMF just before overtopping the dam.

The computed one percent chance flood using 100-year 24 hour rainfall data was routed through the reservoir. The routing results indicate that the spillway/reservoir system will accommodate the 100-year flood without overtopping the dam.

The failure of the dam could cause extensive damage to the property downstream of the dam and possible loss of life. Within the estimated five mile damage zone downstream of the dam are seven houses, six buildings and one road crossing.

SECTION 6: STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Observations

There were no signs of settlement or distress observed on the embankment or foundation during the visual inspection. The upstream slope of the embankment is exhibiting sloughing and erosion due to wave action. The condition does not appear to be serious at this time, but the condition should be watched and the slope stabilized as required.

Seepage observed during the inspection is not believed to be serious enough to indicate an unsafe condition at this time. However, the seepage should be monitored and any changes in quantity, location or color should be reported and investigated. The recommended seepage and stability study should address this seepage in detail.

The spillway discharge channel should be cleared of all trees and large brush, and future growth should be prevented. The structural condition of the spillway weir is satisfactory. The discharge channel, however, is undergoing substantial erosion on the earthen banks of the channel. The erosion on the left bank is especially hazardous for the structural integrity of the embankment. The discharge channel is separated from the embankment by a thin wall of material, and continued erosion of the bank will eventually cause the bank to fail, allowing discharges to flow along the abutment contact of the dam. The owner has recently added some riprap

to the channel, but more riprap is required to adequately stabilize the bank of the channel.

b. Design and Construction Data

No design or construction data relating to the structural stability of the dam or appurtenant structures were found.

c. Operating Records

No operating records are available relating to the stability of the dam or appurtenant structures. Water levels in the reservoir have not been recorded, however, the reservoir was almost full on the day of inspection, and is assumed to be close to full at all time.

d. Post Construction Changes

The construction in 1977 of a core trench and the addition of material to the downstream embankment slope is a post construction change. This work probably increased the structural stability at the time it was done if the work was performed properly.

e. Seismic Stability

According to the Seismic Zone Map of Contiguous States, Form TM 5-809-10/NAVFAC P.355/AFM 88-3 Chapter 13; April 1973 the portion of Missouri in which B & K Lake No. 1 Dam is located is in Seismic Zone 2. This means there is only moderate damage probability. A detailed seismic analysis is not felt to be necessary for this embankment under present conditions.

SECTION 7: ASSESSMENT/REMEDIAL MEASURES

7.1 Dam Assessment

The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

It should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team.

It is also important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that an unsafe condition could be detected.

a. Safety

The spillway capacity of B & K Lake No. 1 Dam was found to be "Seriously Indadequate". The spillway/reservoir system will accommodate only 17 percent of the PMF before overtopping the dam. The dam is overtopped by more than 1 1/2 feet during the PMF. The duration of overflow is over 6 hours. Overtopping could result in dam failure. If the body of the dam is made up of silty soils the probability of failure of the dam due to overtopping will increase.

The seepage observed below the downstream toe near the left and right abutments and in the spillway channel is not felt to indicate an unsafe condition at present. This seepage should be monitored for changes indicating a potential hazard. The recommended study should determine the cause and effect of the seepage.

The sloughing and erosion on the upstream embankment slope does not appear to be affecting the safety of the dam at this time, but the condition should be monitored and repairs made as required.

The spillway discharge channel is in need of remedial measures. The trees and brush in the spillway channel should be cleared, and future growth prevented. The vegetation in the channel will substantially reduce the hydraulic efficiency of the spillway.

Additional riprap will be required to stabilize the banks of the spillway channel. This should be accomplished in the near future to prevent further erosion of the banks of the channel.

b. Adequacy of Information

Prior information concerning the dam and appurtenant structures is not available. The information presented in this report is based upon visual inspection and simple field measurements.

c. Urgency

The remedial measures recommended in Paragraph 7.2 should be accomplished in the near future. The items recommended in Paragraph 7.2a should be pursued on a high priority basis.

d. Necessity for Phase II Inspection

Based on results of the Phase I inspection, and if the remedial measures recommended in Paragraph 7.2 are undertaken as soon as possible, a Phase II inspection is not felt to be necessary.

7.2 Remedial Measures

a. Alternatives:


Spillway capacity and/or height of dam should be increased to accommodate the PMF without overtopping the dam.

b. O & M Procedures:

1. Seepage and stability analyses should be performed by a professional engineer experienced in the design and construction of dams. This study should concentrate on the area exhibiting seepage on the downstream slope at the right abutment contact.
2. Monitor the condition of the upstream embankment slope, and make repairs to the slope as required.

3. Stabilize the banks of the spillway discharge channel to prevent future erosion and sloughing.
4. Clear the trees and large brush from the spillway discharge channel, and prevent future growth. This work should be done under the supervision of an engineer experienced in the design and construction of earth dams.
5. The owner should initiate the following programs.
 - (a) Periodic inspection of the dam by a professional engineer experienced in the design and construction of earthen dams.
 - (b) Set up a maintenance schedule and log all visits to the dam for operation, repairs and maintenance.


PLATES




SCALE

0 1 2 3 4 MILES

LOCATION MAP - B & K LAKE NO. 1 DAM




PLAN




ELEVATION

SCALE
1" = 100' (HORIZONTAL)
VERTICAL (NOT TO SCALE)




B & K LAKE NO. 1 DAM (MO. 30506)
PLAN AND ELEVATION



<u>QUATERNARY</u>	{ Qal - ALLUVIUM	
<u>PENNSYLVANIAN</u>	{ Pm - MARMATON GROUP	
	{ Pcc - CHEROKEE GROUP	
	{ Mm - ST. LOUIS LIMESTONE	<u>ORDOVICIAN</u>
		SALEM FORMATION
		WARSAW FORMATION
<u>MISSISSIPPIAN</u>	{ Mo - BURLINGTON-KEOKUK FORMATION	
	{ Mk - CHOTEAU GROUP	
		Ouc- NOIX LIMESTONE
		MAQUOKETA SHALE
		CAPE LIMESTONE
		KIMMSWICK FORMATION
		DECORAH FORMATION
		PLATTIN FORMATION
		JOACHIM DOLOMITE
		Osp-ST. PETER SANDSTONE
		Ojc-COTTER-POWELL FORMATION
		JEFFERSON CITY DOLOMITE

X LOCATION OF DAM MO. 30506

REFERENCE:
GEOLOGIC MAP OF MISSOURI,
MISSOURI GEOLOGIC SURVEY,
1979.





GEOLOGIC MAP OF WARREN COUNTY AND ADJACENT AREA

GENERALIZED GEOLOGIC MAP OF MISSOURI

GEOLOGY AND LAND SURVEY, DEPT. OF NATURAL RESOURCES
Warren B. Hume, Director & State Geologist
Rolla, Mo. 65401
1978

- LEGEND**
- 6 Tertiary-Quaternary
 - 5 Cretaceous
 - 4 Permian
 - 3 Mississippian
 - 2 Silurian
 - 1 Devonian
 - 0 Ordovician
 - 2 Cambrian
 - 1 Precambrian
 - 0 Not Placed (No full and complete record shown)
- Capital Area, New Capital Centered at 181°-182°
- Other Selected Ep. centers > MM VI Since 1843
- Other Selected Ep. centers > MM V 1850-1970 (Number of Events)
- Santa Fe Region (After Nat'l.)
- Border of Warren County





APPENDIX A

PHOTOGRAPHS TAKEN DURING INSPECTION




PHOTO INDEX
FOR
B & K LAKE NO. 1 DAM


B & K Lake No.1 Dam

- D1 - Upstream embankment slope
- D2 - Crest of embankment slope
- D3 - Downstream embankment slope
- D4 - Downstream embankment slope
- D5 - View downstream of embankment
- D6 - Spillway approach
- D7 - Concrete weir in spillway channel
- D8 - Pipes through concrete weir
- D9 - Spillway discharge channel
- D10- View downstream of embankment



D1

D2






D3



D4



D5



D6



D7



D8



D9




D10

APPENDIX B

HYDROLOGIC COMPUTATIONS

PLATE I, APPENDIX B



B & K LAKE NO. 1 DAM (MO. 30506)
DRAINAGE BASIN

Dam Safety Inspection - Missouri


SHEET NO. 1 OF 1

BOK LAKE No 4. Dam

JOB NO. 1246

3. PILEWAY AND OVERTOP


BY ABW DATE 9-4-76



$$A^2 \pi^2 = 0.785 \text{ ft}^2$$

[illegible]

PLATE 2, APPENDIX-B



B & K LAKE NO. 1 DAM (MO. 30506)
SPILLWAY AND OVERTOP RATING CURVE

DAM SAFETY INSPECTION - MISSOURI

SHEET NO. 1 OF


B&K Lake No. 2 Dam, Upstream of B&K Lake No. 2 Dam

JOB NO. 1240-001-1

EMERGENCY SPILLWAY AND OVERTOP RATING CURVE BY KLG


DATE 5.21.77

CRITICAL DEPTH ASSUMED IN SPILLWAY SECTION.




Y_1 (FEET)	A_1 (FEET ²)	T_1 (FEET)	$V_1 = \sqrt{\frac{A_1}{T_1}}$ $5.67 \sqrt{\frac{A_1}{T_1}}$	$\frac{V_1^2}{2g}$	$Q_1 = \frac{A_1 V_1}{C_1}$ (CFS)	$\frac{1}{5} W.S.$ $= 855 + \frac{V_1^2}{2g} + Y_1$	H_2	C_2	L_2	$Q_2 = \frac{A_2 V_2}{C_2}$ $C_2 L_2 \frac{H_2}{5}$	$Q = Q_1 + Q_2$
0	0	0	0	0	0	855	-	-	-	-	0
.5	3.58	14.33	2.84	0.12	10.17	855.62	-	-	-	-	10.17
1	14.33	28.67	4.01	0.25	52.46	856.25	-	-	-	-	57.46
1.5	32.25	43.0	4.91	0.37	158.35	856.87	.37	2.70	298	181.09	339.44
2.0	53.75	43.0	6.34	0.62	340.78	857.62	1.12	2.64	298	932.5	1273.28
2.5	75.25	43.0	7.50	0.87	544.38	858.57	1.87	2.63	298	2004.1	2568.55
3.0	96.75	43.0	8.51	1.12	823.34	859.12	2.62	2.63	298	3333.7	4147.06
3.5	118.25	43.0	9.40	1.37	1111.5	859.87	3.37	2.63	298	4848.6	5960.16
4.0	139.75	43.0	10.22	1.62	1428.25	860.62	4.12	2.63	298	6554.2	7982.42

PLATE-3, APPENDIX-B



B & K LAKE NO. 2 DAM
SPILLWAY & OVERTOP RATING CURVE

PLATE-4, APPENDIX-B



B & K LAKE NO. 1 DAM (MO. 30506)
RESERVOIR CAPACITY CURVE

ENGINEERING CONSULTANTS, INC.

Dam Safety Inspection - Missouri
B&K Lake No. 2 Dam Upstream of B&K Lake No. 1
RESERVOIR AREA CAPACITY


SHEET NO. 1 OF

JOB NO. 1240

BY M.P.H. DATE 6-1-79

B&K Lake No. 2 DamRESERVOIR AREA CAPACITY

Elev. M.S.L. (Ft.)	Reservoir Surface Area (Acres)	Incremental Volume (Ac.-ft.)	Total Volume (Ac.-ft.)	Remarks
830	0	0	0	Est. streambed Elev. at Dam.
855	4.7	39.2	39.2	U.S. as shown on U.S.G.S map (Elev. Assumed)
856.5	5.1	7.3	46.5	Top of Dam.
860	6.1	19.6	66.1	Area as measured on U.S.G.S. map.
880	13.4	190.3	266.4	Area as measured on U.S.G.S. map.



B & K LAKE NO. 2 DAM
RESERVOIR CAPACITY CURVE

DAM SAFETY INSPECTION / MISSOURI

SHEET NO. 4 OF

DAM # MO 30506

JOB NO. 1240-001

PROBABLE MAXIMUM PRECIPITATION

BY MAB DATE 5/22/77

DAM NO MO 30506

DETERMINATION OF PMP

1. Determine drainage area of the basin

D.A. = 157 Ac = 0.25 sq. mi

2. Determine PMP Index Rainfall


Location of centroid of basin.

Long. = $91^{\circ}12'57''$, Lat. = $38^{\circ}40'59''$, \Rightarrow PMP = 24"
(From HMR #33, Fig 1)

3. Determine basin rainfall in terms of percentage of PMP Index Rainfall for various durations:

Location: Long. = $91^{\circ}12'57''$, Lat. = $38^{\circ}40'59''$ \Rightarrow Zone 7

Duration (Hrs.)	Percent of Index Rainfall (%)	Total Rainfall (inches)	Rainfall Increment (inches)	Duration of Increment (Hrs.)
6	100	24	24	6
12	120	28.8	4.8	6
24	130	31.2	2.4	12



B&K Lake No. 1 Dam (MO. 30506)
 LOCATION OF CENTROID OF WATERSHED
 LAT. = 38° 40' 59", LONG. = 91° 12' 57"

PMP FOR 200 SQ. MI. - 24 HRS
 DURATION = 24"




FIGURE 2
SEASONAL VARIATION
DEPTH-AREA-DURATION RELATIONSHIPS
Percentage to be applied to 200 square miles
24 hour probable maximum precipitation values
for: THE-ALL SEASON ENVELOPE

DAM SAFETY INSPECTION / MISSOURI

SHEET NO. 1 OF

B&K Lake No. 1 Dam (MO. 30506)

JOB NO. 1240-001

UNIT HYDROGRAPH PARAMETERS

BY MAB DATE 6-4-75

1. Drainage Area = 132 acres = 0.21 Sq. mi.
2. Length of stream = $(1.00 \times 2000' / 5280) = 0.38 \text{ miles}$
3. Elevation of drainage divide along the longest stream, $H_1 = 900'$
4. Reservoir elevation at spillway crest, $H_2 = 830'$
5. Difference in elevation, $\Delta H = 900 - 830 = 70'$
6. Time of concentration

a) By Kimpich formula:

$$T_c = \left(\frac{11.9 \times L^3}{\Delta H} \right)^{0.385} = \left(\frac{11.9 \times 0.38^3}{70} \right)^{0.385}$$

$$= 0.17 \text{ hr.}$$

b) By velocity estimate:

$$\text{Avg. Slope} = \frac{\Delta H}{L} = \frac{70}{2000} = 3.5\%$$

$$\Rightarrow \text{Avg. Velocity} = 3 \text{ ft/sec}$$

$$T_c = \frac{2000}{3 \times 60 \times 60} = 0.19 \text{ hr.}$$

$$\text{Use } T_c = 0.18 \text{ hr}$$

7. Lag time, $L_t = 0.6 \times 0.18 = 0.11 \text{ hr.}$
8. Unit duration, $D \leq \frac{L_t}{3} = 0.04 < 0.083$
- Use $D = 0.083 \text{ hr.}$

$$9. \text{ Time to peak, } T_p = \frac{D}{2} + L_t = \frac{0.083}{2} + 0.11 = 0.15 \text{ hr.}$$

$$10. Q_p = \frac{484A}{T_p} = \frac{484 \times 0.21}{0.15} = 678 \text{ cfs.}$$

DAM SAFETY INSPECTION / MISSOURI

SHEET NO. 1 OF

B&K Lake No. 2 Dam U/s of B&K Lake No. 1 Dam

JOB NO. 1240-001

UNIT HYDROGRAPH PARAMETERS

BY MAS DATE 6-178

1. Drainage Area = 25 acres = 0.089 sq. mi.
2. Length of stream = $(0.35 \times 2000 / 5280 \text{ ft/mi}) = 0.13 \text{ miles}$
3. Elevation at drainage divide along the longest stream, $H_1 = 905'$
4. Reservoir elevation at spillway crest $H_2 = 855'$
5. Difference in elevation, $\Delta H = 905 - 855 = 50'$
6. Average slope of stream = $\frac{\Delta H}{L} = \frac{50}{700} = 7.14\%$
7. Time of concentration

a) By Kirpich formula:

$$T_c = \left(\frac{11.9 \times L^3}{\Delta H} \right)^{0.385} = \left(\frac{11.9 \times 13^3}{50} \right)^{0.385}$$

$$= 0.06 \text{ hour}$$

b) By velocity estimate:

$$\text{Avg slope} = 7.14\% \Rightarrow \text{Avg velocity} \approx 3.8 \text{ ft/sec}$$

$$T_c = \frac{700}{5 \times 3600} = 0.04 \text{ hr.}$$

Use $T_c = 0.083 \text{ hr}$ to meet the Corps criteria of Minimum $D = 5 \text{ minutes}$

$$8. \text{Lag time, } L_t = 0.6 \times 0.083 = 0.05 \text{ hr.}$$

9. Unit duration: Use Minimum $D = 5 \text{ minutes}$ to meet the Corps criteria

$$10. \text{Time to peak, } T_p = \frac{D}{2} + L_t = \frac{0.083}{2} + 0.05 = 0.092 \text{ hr.}$$

$$11. Q_p = \frac{484A}{T_p} = \frac{484 \times 0.039}{0.092} = 205 \text{ cfs}$$

DAM SAFETY INSPECTION / MISSOURI

SHEET NO. 1 OF

B&K LAKE NO. 1 DAM (MO. 30506)

JOB NO. 1240-001

DETERMINATION OF SOIL GROUP & CURVE NUMBER BY MAS DATE 6-1-79

MISSOURI DAM # MO. 30506DETERMINATION OF HYDROLOGIC SOIL GROUP & SCS CURVE NUMBER

1. The soils in the watershed consist of C&D group soils. The 'C' group soil seems to be predominant.

Assume soil group 'C' for the entire watershed.

2. Most of the watershed is wooded and covered with grass. Assume 'Fair' condition for infiltration purpose.
thus

CN = 73 for soil group 'C' & AMC-II

⇒ CN = 87 for AMC-III.

DAM SAFETY INSPECTION / MISSOURI

SHEET NO. 1 OF

B&K Lake No. 2 Dam U/S of B&K Lake No. 1 Dam JOB NO. 1240-001

DETERMINATION OF SOIL GROUP & CURVE NUMBER BY MAS DATE 6-1-79

B&K LAKE NO. 2 DAM UPSTREAM OF B&K LAKE NO. 1 DAMDETERMINATION OF HYDROLOGIC SOIL GROUP & SCS CURVE NUMBER

1. The soils in the watershed consist of C & D group soils but D group soil is predominant

Assume 'D' group soil for this watershed.

2. Most of the watershed area is wooded and covered with grass. Assume 'Fair' condition for infiltration.

Thus $CN = 79$ for soil group D & AMC-II

⇒ $CN = 91$ for AMC-III.

HEC1DB INPUT DATA

INFLOW PMF AND ONE-HALF PMF HYDROGRAPHS

C

REVIEW OF SEQUENCE OF STAFF VEHICLE CALCULATIONS

ROUTE HYDROGRAPH AT 0751
ROUTE HYDROGRAPH TO 0751
ROUTE HYDROGRAPH AT 0806
ROUTE HYDROGRAPH AT 0806
ROUTE HYDROGRAPH TO 0806
END OF REVIEW

091940 - 10.11.1940
060700 - 10.11.1940

DAM SAFETY INSPECTION - MISSOURI
 D AND K LAKE NO. 1 DAM 709261
 2000 AND 2001 PERCENT OF DETERMINATION AND ROUTING

[illegible]

02-06-1978

STJIE 100,000,000

513-236: 20.0KF COMP. 74710V

RELATIVE SOLUBILIZATION IN EX. RATIOS AND UNIT HYDROGRAPH PARAMETERS

ISTAG	ICJAP	IFCON	ITAPC	JPLY	JPT	INAME	ISTAGE	TAUD
11/51	2	0	9	0	0	1	0	0

[illegible]

	PMS	R6	R12	R24	R48	R72	R96
SPFC	24.00	100.00	126.00	170.00	0.00	0.00	0.00
RECEIVED DATA							

LOSS DATA		STOCKS		BOND		CASH		TOTAL	
NO. OF	PERCENT	NO. OF	PERCENT	NO. OF	PERCENT	NO. OF	PERCENT	NO. OF	PERCENT
100	100.00	100	100.00	100	100.00	100	100.00	100	100.00
90	90.00	90	90.00	90	90.00	90	90.00	90	90.00
80	80.00	80	80.00	80	80.00	80	80.00	80	80.00
70	70.00	70	70.00	70	70.00	70	70.00	70	70.00
60	60.00	60	60.00	60	60.00	60	60.00	60	60.00
50	50.00	50	50.00	50	50.00	50	50.00	50	50.00
40	40.00	40	40.00	40	40.00	40	40.00	40	40.00
30	30.00	30	30.00	30	30.00	30	30.00	30	30.00
20	20.00	20	20.00	20	20.00	20	20.00	20	20.00
10	10.00	10	10.00	10	10.00	10	10.00	10	10.00
0	0.00	0	0.00	0	0.00	0	0.00	0	0.00

UNIT HYDROGRAPH DATA
ICE 10:00 LAG 05

DATE	RECESSION DATA	RECESSION DATA
0.00	0.00	0.00

TIME INCREMENT TOO LARGE--(WHO IS GT LAG/2)

UNIT HYDROGRAPH 5 END OF PERIOD ORDINATES, ICE 0.00 HOURS, 1.00 VOL=1.00

239.	77.	193	4.	1.	IMP-OF-REPROD FLD.	COMP Q	LOSS	RACS	RAIR	DE-12	10-MA	239.
1.00	1	2.00	.01	0.	1.01	0.	.01	2.00	1	1.00	1.00	1.00
1.01	1	3.00	.01	0.	1.01	0.	.01	3.00	1	1.01	1.01	1.01
1.02	1	4.00	.01	0.	1.01	0.	.01	4.00	1	1.01	1.02	1.02
1.03	1	5.00	.01	0.	1.01	0.	.01	5.00	1	1.01	1.03	1.03
1.04	1	6.00	.01	0.	1.01	0.	.01	6.00	1	1.01	1.04	1.04
1.05	1	7.00	.01	0.	1.01	0.	.01	7.00	1	1.01	1.05	1.05
1.06	1	8.00	.01	0.	1.01	0.	.01	8.00	1	1.01	1.06	1.06
1.07	1	9.00	.01	0.	1.01	0.	.01	9.00	1	1.01	1.07	1.07
1.08	1	10.00	.01	0.	1.01	0.	.01	10.00	1	1.01	1.08	1.08
1.09	1	11.00	.01	0.	1.01	0.	.01	11.00	1	1.01	1.09	1.09
1.10	1	12.00	.01	0.	1.01	0.	.01	12.00	1	1.01	1.10	1.10
1.11	1	13.00	.01	0.	1.01	0.	.01	13.00	1	1.01	1.11	1.11
1.12	1	14.00	.01	0.	1.01	0.	.01	14.00	1	1.01	1.12	1.12
1.13	1	15.00	.01	0.	1.01	0.	.01	15.00	1	1.01	1.13	1.13
1.14	1	16.00	.01	0.	1.01	0.	.01	16.00	1	1.01	1.14	1.14
1.15	1	17.00	.01	0.	1.01	0.	.01	17.00	1	1.01	1.15	1.15
1.16	1	18.00	.01	0.	1.01	0.	.01	18.00	1	1.01	1.16	1.16
1.17	1	19.00	.01	0.	1.01	0.	.01	19.00	1	1.01	1.17	1.17
1.18	1	20.00	.01	0.	1.01	0.	.01	20.00	1	1.01	1.18	1.18
1.19	1	21.00	.01	0.	1.01	0.	.01	21.00	1	1.01	1.19	1.19
1.20	1	22.00	.01	0.	1.01	0.	.01	22.00	1	1.01	1.20	1.20
1.21	1	23.00	.01	0.	1.01	0.	.01	23.00	1	1.01	1.21	1.21
1.22	1	24.00	.01	0.	1.01	0.	.01	24.00	1	1.01	1.22	1.22
1.23	1	25.00	.01	0.	1.01	0.	.01	25.00	1	1.01	1.23	1.23
1.24	1	26.00	.01	0.	1.01	0.	.01	26.00	1	1.01	1.24	1.24
1.25	1	27.00	.01	0.	1.01	0.	.01	27.00	1	1.01	1.25	1.25
1.26	1	28.00	.01	0.	1.01	0.	.01	28.00	1	1.01	1.26	1.26
1.27	1	29.00	.01	0.	1.01	0.	.01	29.00	1	1.01	1.27	1.27
1.28	1	30.00	.01	0.	1.01	0.	.01	30.00	1	1.01	1.28	1.28
1.29	1	31.00	.01	0.	1.01	0.	.01	31.00	1	1.01	1.29	1.29
1.30	1	32.00	.01	0.	1.01	0.	.01	32.00	1	1.01	1.30	1.30
1.31	1	33.00	.01	0.	1.01	0.	.01	33.00	1	1.01	1.31	1.31
1.32	1	34.00	.01	0.	1.01	0.	.01	34.00	1	1.01	1.32	1.32
1.33	1	35.00	.01	0.	1.01	0.	.01	35.00	1	1.01	1.33	1.33
1.34	1	36.00	.01	0.	1.01	0.	.01	36.00	1	1.01	1.34	1.34
1.35	1	37.00	.01	0.	1.01	0.	.01	37.00	1	1.01	1.35	1.35
1.36	1	38.00	.01	0.	1.01	0.	.01	38.00	1	1.01	1.36	1.36
1.37	1	39.00	.01	0.	1.01	0.	.01	39.00	1	1.01	1.37	1.37
1.38	1	40.00	.01	0.	1.01	0.	.01	40.00	1	1.01	1.38	1.38
1.39	1	41.00	.01	0.	1.01	0.	.01	41.00	1	1.01	1.39	1.39
1.40	1	42.00	.01	0.	1.01	0.	.01	42.00	1	1.01	1.40	1.40
1.41	1	43.00	.01	0.	1.01	0.	.01	43.00	1	1.01	1.41	1.41
1.42	1	44.00	.01	0.	1.01	0.	.01	44.00	1	1.01	1.42	1.42
1.43	1	45.00	.01	0.	1.01	0.	.01	45.00	1	1.01	1.43	1.43
1.44	1	46.00	.01	0.	1.01	0.	.01	46.00	1	1.01	1.44	1.44
1.45	1	47.00	.01	0.	1.01	0.	.01	47.00	1	1.01	1.45	1.45
1.46	1	48.00	.01	0.	1.01	0.	.01	48.00	1	1.01	1.46	1.46
1.47	1	49.00	.01	0.	1.01	0.	.01	49.00	1	1.01	1.47	1.47
1.48	1	50.00	.01	0.	1.01	0.	.01	50.00	1	1.01	1.48	1.48
1.49	1	51.00	.01	0.	1.01	0.	.01	51.00	1	1.01	1.49	1.49
1.50	1	52.00	.01	0.	1.01	0.	.01	52.00	1	1.01	1.50	1.50
1.51	1	53.00	.01	0.	1.01	0.	.01	53.00	1	1.01	1.51	1.51
1.52	1	54.00	.01	0.	1.01	0.	.01	54.00	1	1.01	1.52	1.52
1.53	1	55.00	.01	0.	1.01	0.	.01	55.00	1	1.01	1.53	1.53

.....

.....

.....

.....

.....

SALE: HERE YOU ARE

NOTHING BUT THE TRUTH - TAKE NO BAWD

1971
dated 10-21-1971
with 1707
Total 3,812.1
C1000

100

[illegible]

1. *Chlorophyll a* (Chl *a*)
 2. *Chlorophyll b* (Chl *b*)
 3. *Chlorophyll c* (Chl *c*)
 4. *Chlorophyll d* (Chl *d*)
 5. *Chlorophyll e* (Chl *e*)
 6. *Chlorophyll f* (Chl *f*)
 7. *Chlorophyll g* (Chl *g*)
 8. *Chlorophyll h* (Chl *h*)
 9. *Chlorophyll i* (Chl *i*)
 10. *Chlorophyll j* (Chl *j*)
 11. *Chlorophyll k* (Chl *k*)
 12. *Chlorophyll l* (Chl *l*)
 13. *Chlorophyll m* (Chl *m*)
 14. *Chlorophyll n* (Chl *n*)
 15. *Chlorophyll o* (Chl *o*)
 16. *Chlorophyll p* (Chl *p*)
 17. *Chlorophyll q* (Chl *q*)
 18. *Chlorophyll r* (Chl *r*)
 19. *Chlorophyll s* (Chl *s*)
 20. *Chlorophyll t* (Chl *t*)
 21. *Chlorophyll u* (Chl *u*)
 22. *Chlorophyll v* (Chl *v*)
 23. *Chlorophyll w* (Chl *w*)
 24. *Chlorophyll x* (Chl *x*)
 25. *Chlorophyll y* (Chl *y*)
 26. *Chlorophyll z* (Chl *z*)
 27. *Chlorophyll aa* (Chl *aa*)
 28. *Chlorophyll ab* (Chl *ab*)
 29. *Chlorophyll ac* (Chl *ac*)
 30. *Chlorophyll ad* (Chl *ad*)
 31. *Chlorophyll ae* (Chl *ae*)
 32. *Chlorophyll af* (Chl *af*)
 33. *Chlorophyll ag* (Chl *ag*)
 34. *Chlorophyll ah* (Chl *ah*)
 35. *Chlorophyll ai* (Chl *ai*)
 36. *Chlorophyll aj* (Chl *aj*)
 37. *Chlorophyll ak* (Chl *ak*)
 38. *Chlorophyll al* (Chl *al*)
 39. *Chlorophyll am* (Chl *am*)
 40. *Chlorophyll an* (Chl *an*)
 41. *Chlorophyll ao* (Chl *ao*)
 42. *Chlorophyll ap* (Chl *ap*)
 43. *Chlorophyll aq* (Chl *aq*)
 44. *Chlorophyll ar* (Chl *ar*)
 45. *Chlorophyll as* (Chl *as*)
 46. *Chlorophyll at* (Chl *at*)
 47. *Chlorophyll au* (Chl *au*)
 48. *Chlorophyll av* (Chl *av*)
 49. *Chlorophyll aw* (Chl *aw*)
 50. *Chlorophyll ax* (Chl *ax*)
 51. *Chlorophyll ay* (Chl *ay*)
 52. *Chlorophyll az* (Chl *az*)
 53. *Chlorophyll aza* (Chl *aza*)
 54. *Chlorophyll abz* (Chl *abz*)
 55. *Chlorophyll acz* (Chl *acz*)
 56. *Chlorophyll adz* (Chl *adz*)
 57. *Chlorophyll aez* (Chl *aez*)
 58. *Chlorophyll afz* (Chl *afz*)
 59. *Chlorophyll agz* (Chl *agz*)
 60. *Chlorophyll ahz* (Chl *ahz*)
 61. *Chlorophyll aiz* (Chl *aiz*)
 62. *Chlorophyll ajz* (Chl *ajz*)
 63. *Chlorophyll akz* (Chl *akz*)
 64. *Chlorophyll alz* (Chl *alz*)
 65. *Chlorophyll amz* (Chl *amz*)
 66. *Chlorophyll anz* (Chl *anz*)
 67. *Chlorophyll aoz* (Chl *aoz*)
 68. *Chlorophyll apz* (Chl *apz*)
 69. *Chlorophyll aqz* (Chl *aqz*)
 70. *Chlorophyll arz* (Chl *arz*)
 71. *Chlorophyll asz* (Chl *asz*)
 72. *Chlorophyll atz* (Chl *atz*)
 73. *Chlorophyll auz* (Chl *auz*)
 74. *Chlorophyll avz* (Chl *avz*)
 75. *Chlorophyll awz* (Chl *awz*)
 76. *Chlorophyll axz* (Chl *axz*)
 77. *Chlorophyll ayz* (Chl *ayz*)
 78. *Chlorophyll ayz* (Chl *ayz*)
 79. *Chlorophyll azz* (Chl *azz*)
 80. *Chlorophyll azaa* (Chl *aza*)
 81. *Chlorophyll abz* (Chl *abz*)
 82. *Chlorophyll acz* (Chl *acz*)
 83. *Chlorophyll adz* (Chl *adz*)
 84. *Chlorophyll aez* (Chl *aez*)
 85. *Chlorophyll afz* (Chl *afz*)
 86. *Chlorophyll agz* (Chl *agz*)
 87. *Chlorophyll ahz* (Chl *ahz*)
 88. *Chlorophyll aiz* (Chl *aiz*)
 89. *Chlorophyll ajz* (Chl *ajz*)
 90. *Chlorophyll akz* (Chl *akz*)
 91. *Chlorophyll alz* (Chl *alz*)
 92. *Chlorophyll amz* (Chl *amz*)
 93. *Chlorophyll anz* (Chl *anz*)
 94. *Chlorophyll aoz* (Chl *aoz*)
 95. *Chlorophyll apz* (Chl *apz*)
 96. *Chlorophyll aqz* (Chl *aqz*)
 97. *Chlorophyll arz* (Chl *arz*)
 98. *Chlorophyll asz* (Chl *asz*)
 99. *Chlorophyll atz* (Chl *atz*)
 100. *Chlorophyll auz* (Chl *auz*)
 101. *Chlorophyll avz* (Chl *avz*)
 102. *Chlorophyll awz* (Chl *awz*)
 103. *Chlorophyll axz* (Chl *axz*)
 104. *Chlorophyll ayz* (Chl *ayz*)
 105. *Chlorophyll ayz* (Chl *ayz*)
 106. *Chlorophyll ayz* (Chl *ayz*)
 107. *Chlorophyll ayz* (Chl *ayz*)
 108. *Chlorophyll ayz* (Chl *ayz*)
 109. *Chlorophyll ayz* (Chl *ayz*)
 110. *Chlorophyll ayz* (Chl *ayz*)
 111. *Chlorophyll ayz* (Chl *ayz*)
 112. *Chlorophyll ayz* (Chl *ayz*)
 113. *Chlorophyll ayz* (Chl *ayz*)
 114. *Chlorophyll ayz* (Chl *ayz*)
 115. *Chlorophyll ayz* (Chl *ayz*)
 116. *Chlorophyll ayz* (Chl *ayz*)
 117. *Chlorophyll ayz* (Chl *ayz*)
 118. *Chlorophyll ayz* (Chl *ayz*)
 119. *Chlorophyll ayz* (Chl *ayz*)
 120. *Chlorophyll ayz* (Chl *ayz*)
 121. *Chlorophyll ayz* (Chl *ayz*)
 122. *Chlorophyll ayz* (Chl *ayz*)
 123. *Chlorophyll ayz* (Chl *ayz*)
 124. *Chlorophyll ayz* (Chl *ayz*)
 125. *Chlorophyll ayz* (Chl *ayz*)
 126. *Chlorophyll ayz* (Chl *ayz*)
 127. *Chlorophyll ayz* (Chl *ayz*)
 128. *Chlorophyll ayz* (Chl *ayz*)
 129. *Chlorophyll ayz* (Chl *ayz*)
 130. *Chlorophyll ayz* (Chl *ayz*)
 131. *Chlorophyll ayz* (Chl *ayz*)
 132. *Chlorophyll ayz* (Chl *ayz*

[illegible]

1950-1951

Time	Lat	Long	Alt	Wind	Temp	Humid	Clouds	Pressure	Remarks
0000	10 00	100 00	1000	000	100	100	000	1000	0000
0100	10 00	100 00	1000	000	100	100	000	1000	0100
0200	10 00	100 00	1000	000	100	100	000	1000	0200
0300	10 00	100 00	1000	000	100	100	000	1000	0300
0400	10 00	100 00	1000	000	100	100	000	1000	0400
0500	10 00	100 00	1000	000	100	100	000	1000	0500
0600	10 00	100 00	1000	000	100	100	000	1000	0600
0700	10 00	100 00	1000	000	100	100	000	1000	0700
0800	10 00	100 00	1000	000	100	100	000	1000	0800
0900	10 00	100 00	1000	000	100	100	000	1000	0900
1000	10 00	100 00	1000	000	100	100	000	1000	1000
1100	10 00	100 00	1000	000	100	100	000	1000	1100
1200	10 00	100 00	1000	000	100	100	000	1000	1200
1300	10 00	100 00	1000	000	100	100	000	1000	1300
1400	10 00	100 00	1000	000	100	100	000	1000	1400
1500	10 00	100 00	1000	000	100	100	000	1000	1500
1600	10 00	100 00	1000	000	100	100	000	1000	1600
1700	10 00	100 00	1000	000	100	100	000	1000	1700
1800	10 00	100 00	1000	000	100	100	000	1000	1800
1900	10 00	100 00	1000	000	100	100	000	1000	1900
2000	10 00	100 00	1000	000	100	100	000	1000	2000
2100	10 00	100 00	1000	000	100	100	000	1000	2100
2200	10 00	100 00	1000	000	100	100	000	1000	2200
2300	10 00	100 00	1000	000	100	100	000	1000	2300
2400	10 00	100 00	1000	000	100	100	000	1000	2400

47. 5. 36.

17. 680.

[illegible][illegible]

0.14

Year	1955	1956	1957	1958	1959	1960	1961	1962	1963	1964	1965	1966	1967	1968	1969	1970	1971	1972	1973	1974	1975	1976	1977	1978	1979	1980	1981	1982	1983	1984	1985	1986	1987	1988	1989	1990	1991	1992	1993	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055	2056	2057	2058	2059	2060	2061	2062	2063	2064	2065	2066	2067	2068	2069	2070	2071	2072	2073	2074	2075	2076	2077	2078	2079	2080	2081	2082	2083	2084	2085	2086	2087	2088	2089	2090	2091	2092	2093	2094	2095	2096	2097	2098	2099	2100
1955	1956	1957	1958	1959	1960	1961	1962	1963	1964	1965	1966	1967	1968	1969	1970	1971	1972	1973	1974	1975	1976	1977	1978	1979	1980	1981	1982	1983	1984	1985	1986	1987	1988	1989	1990	1991	1992	1993	1994	1995	1996	1997	1998	1999	2000	2001	2002	2003	2004	2005	2006	2007	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018	2019	2020	2021	2022	2023	2024	2025	2026	2027	2028	2029	2030	2031	2032	2033	2034	2035	2036	2037	2038	2039	2040	2041	2042	2043	2044	2045	2046	2047	2048	2049	2050	2051	2052	2053	2054	2055	2056	2057	2058	2059	2060	2061	2062	2063	2064	2065	2066	2067	2068	2069	2070	2071	2072	2073	2074	2075	2076	2077	2078	2079	2080	2081	2082	2083	2084	2085	2086	2087	2088	2089	2090	2091	2092	2093	2094	2095	2096	2097	2098	2099	2100	

STATION 10510 PLAN 10-211

END OF SECTION 1 PAGE 2

SECRET

[illegible][illegible]

100

2000 2001 2002 2003 2004 2005 2006 2007 2008 2009 2010 2011 2012 2013 2014 2015 2016 2017 2018 2019 2020 2021 2022 2023 2024 2025 2026 2027 2028 2029 2030 2031 2032 2033 2034 2035 2036 2037 2038 2039 2040 2041 2042 2043 2044 2045 2046 2047 2048 2049 2050 2051 2052 2053 2054 2055 2056 2057 2058 2059 2060 2061 2062 2063 2064 2065 2066 2067 2068 2069 2070 2071 2072 2073 2074 2075 2076 2077 2078 2079 2080 2081 2082 2083 2084 2085 2086 2087 2088 2089 2090 2091 2092 2093 2094 2095 2096 2097 2098 2099 2100 2101 2102 2103 2104 2105 2106 2107 2108 2109 2110 2111 2112 2113 2114 2115 2116 2117 2118 2119 2120 2121 2122 2123 2124 2125 2126 2127 2128 2129 2130 2131 2132 2133 2134 2135 2136 2137 2138 2139 2140 2141 2142 2143 2144 2145 2146 2147 2148 2149 2150 2151 2152 2153 2154 2155 2156 2157 2158 2159 2160 2161 2162 2163 2164 2165 2166 2167 2168 2169 2170 2171 2172 2173 2174 2175 2176 2177 2178 2179 2180 2181 2182 2183 2184 2185 2186 2187 2188 2189 2190 2191 2192 2193 2194 2195 2196 2197 2198 2199 2200 2201 2202 2203 2204 2205 2206 2207 2208 2209 2210 2211 2212 2213 2214 2215 2216 2217 2218 2219 2220 2221 2222 2223 2224 2225 2226 2227 2228 2229 2230 2231 2232 2233 2234 2235 2236 2237 2238 2239 2240 2241 2242 2243 2244 2245 2246 2247 2248 2249 2250 2251 2252 2253 2254 2255 2256 2257 2258 2259 2260 2261 2262 2263 2264 2265 2266 2267 2268 2269 2270 2271 2272 2273 2274 2275 2276 2277 2278 2279 2280 2281 2282 2283 2284 2285 2286 2287 2288 2289 2290 2291 2292 2293 2294 2295 2296 2297 2298 2299 2300 2301 2302 2303 2304 2305 2306 2307 2308 2309 2310 2311 2312 2313 2314 2315 2316 2317 2318 2319 2320 2321 2322 2323 2324 2325 2326 2327 2328 2329 2330 2331 2332 2333 2334 2335 2336 2337 2338 2339 2340 2341 2342 2343 2344 2345 2346 2347 2348 2349 2350 2351 2352 2353 2354 2355 2356 2357 2358 2359 2360 2361 2362 2363 2364 2365 2366 2367 2368 2369 2370 2371 2372 2373 2374 2375 2376 2377 2378 2379 2380 2381 2382 2383 2384 2385 2386 2387 2388 2389 2390 2391 2392 2393 2394 2395 2396 2397 2398 2399 2400 2401 2402 2403 2404 2405 2406 2407 2408 2409 2410 2411 2412 2413 2414 2415 2416 2417 2418 2419 2420 2421 2422 2423 2424 2425 2426 2427 2428 2429 2430 2431 2432 2433 2434 2435 2436 2437 2438 2439 2440 2441 2442 2443 2444 2445 2446 2447 2448 2449 2450 2451 2452 2453 2454 2455 2456 2457 2458 2459 2460 2461 2462 2463 2464 2465 2466 2467 2468 2469 2470 2471 2472 2473 2474 2475 2476 2477 2478 2479 2480 2481 2482 2483 2484 2485 2486 2487 2488 2489 2490 2491 2492 2493 2494 2495 2496 2497 2498 2499 2500 2501 2502 2503 2504 2505 2506 2507 2508 2509 2510 2511 2512 2513 2514 2515 2516 2517 2518 2519 2520 2521 2522 2523 2524 2525 2526 2527 2528 2529 2530 2531 2532 2533 2534 2535 2536 2537 2538 2539 2540 2541 2542 2543 2544 2545 2546 2547 2548 2549 2550 2551 2552 2553 2554 2555 2556 2557 2558 2559 2560 2561 2562 2563 2564 2565 2566 2567 2568 2569 2570 2571 2572 2573 2574 2575 2576 2577 2578 2579 2580 2581 2582 2583 2584 2585 2586 2587 2588 2589 2590 2591 2592 2593 2594 2595 2596 2597 2598 2599 2600 2601 2602 2603 2604 2605 2606 2607 2608 2609 2610 2611 2612 2613 2614 2615 2616 2617 2618 2619 2620 2621 2622 2623 2624 2625 2626 2627 2628 2629 2630 2631 2632 2633 2634 2635 2636 2637 2638 2639 2640 2641 2642 2643 2644 2645 2646 2647 2648 2649 2650 2651 2652 2653 2654 2655 2656 2657 2658 2659 2660 2661 2662 2663 2664 2665 2666 2667 2668 2669 2670 2671 2672 2673 2674 2675 2676 2677 2678 2679 2680 2681 2682 2683 2684 2685 2686 2687 2688 2689 2690 2691 2692 2693 2694 2695 2696 2697 2698 2699 2700 2701 2702 2703 2704 2705 2706 2707 2708 2709 2710 2711 2712 2713 2714 2715 2716 2717 2718 2719 2720 2721 2722 2723 2724 2725 2726 2727 2728 2729 2730 2731 2732 2733 2734 2735 2736 2737 2738 2739 2740 2741 2742 2743 2744 2745 2746 2747 2748 2749 2750 2751 2752 2753 2754 2755 2756 2757 2758 2759 2760 2761 2762 2763 2764 2765 2766 2767 2768 2769 2770 2771 2772 2773 2774 2775 2776 2777 2778 2779 2780 2781 2782 2783 2784 2785 2786 2787 2788 2789 2790 2791 2792 2793 2794 2795 2796 2797 2798 2799 2800 2801 2802 2803 2804 2805 2806 2807 2808 2809 2810 2811 2812 2813 2814 2815 2816 2817 2818

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200
201
202
203
204
205
206
207
208
209
210
211
212
213
214
215
216
217
218
219
220
221
222
223
224
225
226
227
228
229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251
252
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292
293
294
295
296
297
298
299
300
301
302
303
304
305
306
307
308
309
310
311
312
313
314
315
316
317
318
319
320
321
322
323
324
325
326
327
328
329
330
331
332
333
334
335
336
337
338
339
340
341
342
343
344
345
346
347
348
349
350
351
352
353
354
355
356
357
358
359
360
361
362
363
364
365
366
367
368
369
370
371
372
373
374
375
376
377
378
379
380
381
382
383
384
385
386
387
388
389
390
391
392
393
394
395
396
397
398
399
400
401
402
403
404
405
406
407
408
409
410
411
412
413
414
415
416
417
418
419
420
421
422
423
424
425
426
427
428
429
430
431
432
433
434
435
436
437
438
439
440
441
442
443
444
445
446
447
448
449
450
451
452
453
454
455
456
457
458
459
460
461
462
463
464
465
466
467
468
469
470
471
472
473
474
475
476
477
478
479
480
481
482
483
484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500
501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
560
561
562
563
564
565
566
567
568
569
570
571
572
573
574
575
576
577
578
579
580
581
582
583
584
585
586
587
588
589
590
591
592
593
594
595
596
597
598
599
600
601
602
603
604
605
606
607
608
609
610
611
612
613
614
615
616
617
618
619
620
621
622
623
624
625
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662
663
664
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699
700
701
702
703
704
705
706
707
708
709
710
711
712
713
714
715
716
717
718
719
720
721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741
742
743
744
745
746
747
748
749
750
751
752
753
754
755
756
757
758
759
760
761
762
763
764
765
766
767
768
769
770
771
772
773
774
775
776
777
778
779
780
781
782
783
784
785
786
787
788
789
790
791
792
793
794
795
796
797
798
799
800
801
802
803
804
805
806
807
808
809
810
811
812
813
814
815
816
817
818
819
820
821
822
823
824
825
826
827
828
829
830
831
832
833
834
835
836
837
838
839
840
84

[illegible]

484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500
501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
560
561
562
563
564
565
566
567
568
569
570
571
572
573
574
575
576
577
578
579
580
581
582
583
584
585
586
587
588
589
590
591
592
593
594
595
596
597
598
599
600
601
602
603
604
605
606
607
608
609
610
611
612
613
614
615
616
617
618
619
620
621
622
623
624
625
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662
663
664
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699
700
701
702
703
704
705
706
707
708
709
710
711
712
713
714
715
716
717
718
719
720
721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741
742
743
744
745
746
747
748
749
750
751
752
753
754
755
756
757
758
759
760
761
762
763
764
765
766
767
768
769
770
771
772
773
774
775
776
777
778
779
780
781
782
783
784
785
786
787
788
789
790
791
792
793
794
795
796
797
798
799
800
801
802
803
804
805
806
807
808
809
810
811
812
813
814
815
816
817
818
819
820
821
822
823
824
825
826
827
828
829
830
831
832
833
834
835
836
837
838
839
840
841
842
843
844
845
846
847
848
849
850
851
852
853
854
855
856
857
858
859
860
861
862
863
864
865
866
867
868
869
870
871
872
873
874
875
876
877
878
879
880
881
882
883
884
885
886
887
888
889
890
891
892
893
894
895
896
897
898
899
900
901
902
903
904
905
906
907
908
909
910
911
912
913
914
915
916
917
918
919
920
921
922
923
924
925
926
927
928
929
930
931
932
933
934
935
936
937
938
939
940
941
942
943
944
945
946
947
948
949
950
951
952
953
954
955
956
957
958
959
960
961
962
963
964
965
966
967
968
969
970
971
972
973
974
975
976
977
978
979
980
981
982
983
984
985
986
987
988
989
990
991
992
993
994
995
996
997
998
999
1000

SUMMARY OF PIF AND ONE-HALF PIF FLOOD ROUTING

SUMMARY OF DAM SAFETY ANALYSIS

RATIO OF PPE	MAXIMUM STORAGE OUTFLOW	MAXIMUM STORAGE OVER DAM	MAXIMUM STORAGE OUTFLOW	MAXIMUM STORAGE OUTFLOW	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
1.03	87.42	452	474	1204	15.67	0.00
0.50	236.34	414	474	1931	15.57	0.00

INITIAL VACUE
52.00
52.00
0.00

TOPO OF DA
-56.4
-57.0
-57.0

F/G 13/13

UNCLASSIFIED

DACW43-79-C-0075

NL

2nd 2

Figure 1

END

END
DATE

DATE
FILMED

11-8

DEAD

SUMMARY OF DAM SAFETY ANALYSIS

RATIO OF PPE	MAXIMUM RESERVOIR WATER ELEV.	MAXIMUM STOCK WATER ELEV.	MAXIMUM DURATION OF FAILURE	TIME OF FAILURE	TIME OF FAILURE
1.00	874.55	1.51	1.47	15.75	0.00
1.25	874.55	1.51	1.47	15.75	0.00
1.50	874.55	1.51	1.47	15.75	0.00
1.75	874.55	1.51	1.47	15.75	0.00
2.00	874.55	1.51	1.47	15.75	0.00
2.25	874.55	1.51	1.47	15.75	0.00
2.50	874.55	1.51	1.47	15.75	0.00
2.75	874.55	1.51	1.47	15.75	0.00
3.00	874.55	1.51	1.47	15.75	0.00
3.25	874.55	1.51	1.47	15.75	0.00
3.50	874.55	1.51	1.47	15.75	0.00
3.75	874.55	1.51	1.47	15.75	0.00
4.00	874.55	1.51	1.47	15.75	0.00
4.25	874.55	1.51	1.47	15.75	0.00
4.50	874.55	1.51	1.47	15.75	0.00
4.75	874.55	1.51	1.47	15.75	0.00
5.00	874.55	1.51	1.47	15.75	0.00
5.25	874.55	1.51	1.47	15.75	0.00
5.50	874.55	1.51	1.47	15.75	0.00
5.75	874.55	1.51	1.47	15.75	0.00
6.00	874.55	1.51	1.47	15.75	0.00
6.25	874.55	1.51	1.47	15.75	0.00
6.50	874.55	1.51	1.47	15.75	0.00
6.75	874.55	1.51	1.47	15.75	0.00
7.00	874.55	1.51	1.47	15.75	0.00
7.25	874.55	1.51	1.47	15.75	0.00
7.50	874.55	1.51	1.47	15.75	0.00
7.75	874.55	1.51	1.47	15.75	0.00
8.00	874.55	1.51	1.47	15.75	0.00
8.25	874.55	1.51	1.47	15.75	0.00
8.50	874.55	1.51	1.47	15.75	0.00
8.75	874.55	1.51	1.47	15.75	0.00
9.00	874.55	1.51	1.47	15.75	0.00
9.25	874.55	1.51	1.47	15.75	0.00
9.50	874.55	1.51	1.47	15.75	0.00
9.75	874.55	1.51	1.47	15.75	0.00
10.00	874.55	1.51	1.47	15.75	0.00

PERCENT OF PMF FLOOD ROUTING
EQUAL TO SPILLWAY CAPACITY

[illegible][illegible]

DATE: 10/15/68
TIME: 11:06:44

DAM SAFETY INVESTIGATION - "MICROUR"
 1. A. & L. A. K. E. N. O. I. D. A. M. (30004)
 PERCENT OF DUE DETERMINATION, AND ROUTING

[illegible]

SECTION 101.101 - 11.15.11 - 11.15.11

	16	17	18	19	20	21	22	23
1155-								
1156-								

[illegible]

NEWY CORRELATION INDEX. CALLER AND LIST INTERCOMPARISON

INSTA	ICOD	ICOD	TYPE	UNIT	STAGE	UNIT
0001	0	0	0	0	0	0

[illegible]

	PMS	-	R	PRECIP DATA		
SPFE				310	R24	K96
SA-00	100.00			120.00		9.00
						7.00

[illegible][illegible]

UWIP HYDROGRAPH (ATA)
YC= 0.03 LAC= 0.05

- REFUSION DIA
0.00 DECAY= 0.7
- TIME = 1.00

DATE	TIME	END-OF-PERIOD FLOW	PERIOD	EXCS	LOSS	COMP D
		COND 1	TH-PM			
11-11-77	11:00	100.0	100.0	0.0	0.0	0.0
11-12-77	11:00	100.0	100.0	0.0	0.0	0.0
11-13-77	11:00	100.0	100.0	0.0	0.0	0.0
11-14-77	11:00	100.0	100.0	0.0	0.0	0.0
11-15-77	11:00	100.0	100.0	0.0	0.0	0.0
11-16-77	11:00	100.0	100.0	0.0	0.0	0.0
11-17-77	11:00	100.0	100.0	0.0	0.0	0.0
11-18-77	11:00	100.0	100.0	0.0	0.0	0.0
11-19-77	11:00	100.0	100.0	0.0	0.0	0.0
11-20-77	11:00	100.0	100.0	0.0	0.0	0.0
11-21-77	11:00	100.0	100.0	0.0	0.0	0.0
11-22-77	11:00	100.0	100.0	0.0	0.0	0.0
11-23-77	11:00	100.0	100.0	0.0	0.0	0.0
11-24-77	11:00	100.0	100.0	0.0	0.0	0.0
11-25-77	11:00	100.0	100.0	0.0	0.0	0.0
11-26-77	11:00	100.0	100.0	0.0	0.0	0.0
11-27-77	11:00	100.0	100.0	0.0	0.0	0.0
11-28-77	11:00	100.0	100.0	0.0	0.0	0.0
11-29-77	11:00	100.0	100.0	0.0	0.0	0.0
11-30-77	11:00	100.0	100.0	0.0	0.0	0.0
12-01-77	11:00	100.0	100.0	0.0	0.0	0.0
12-02-77	11:00	100.0	100.0	0.0	0.0	0.0
12-03-77	11:00	100.0	100.0	0.0	0.0	0.0
12-04-77	11:00	100.0	100.0	0.0	0.0	0.0
12-05-77	11:00	100.0	100.0	0.0	0.0	0.0
12-06-77	11:00	100.0	100.0	0.0	0.0	0.0
12-07-77	11:00	100.0	100.0	0.0	0.0	0.0
12-08-77	11:00	100.0	100.0	0.0	0.0	0.0
12-09-77	11:00	100.0	100.0	0.0	0.0	0.0
12-10-77	11:00	100.0	100.0	0.0	0.0	0.0
12-11-77	11:00	100.0	100.0	0.0	0.0	0.0
12-12-77	11:00	100.0	100.0	0.0	0.0	0.0
12-13-77	11:00	100.0	100.0	0.0	0.0	0.0
12-14-77	11:00	100.0	100.0	0.0	0.0	0.0
12-15-77	11:00	100.0	100.0	0.0	0.0	0.0
12-16-77	11:00	100.0	100.0	0.0	0.0	0.0
12-17-77	11:00	100.0	100.0	0.0	0.0	0.0
12-18-77	11:00	100.0	100.0	0.0	0.0	0.0
12-19-77	11:00	100.0	100.0	0.0	0.0	0.0
12-20-77	11:00	100.0	100.0	0.0	0.0	0.0
12-21-77	11:00	100.0	100.0	0.0	0.0	0.0
12-22-77	11:00	100.0	100.0	0.0	0.0	0.0
12-23-77	11:00	100.0	100.0	0.0	0.0	0.0
12-24-77	11:00	100.0	100.0	0.0	0.0	0.0
12-25-77	11:00	100.0	100.0	0.0	0.0	0.0
12-26-77	11:00	100.0	100.0	0.0	0.0	0.0
12-27-77	11:00	100.0	100.0	0.0	0.0	0.0
12-28-77	11:00	100.0	100.0	0.0	0.0	0.0
12-29-77	11:00	100.0	100.0	0.0	0.0	0.0

100

THE NEW YORK PUBLIC LIBRARY

SUMMARY A RUNOFF COMPUTATION

INPUT INDEX, PRECIPITATION, RAINFALL, AND SOCS INPUT HYDROLOGICAL PARAMETER.

TIME	TAKE A	5.20	12.50	18.50	24.50	30.50	36.50	42.50	48.50	54.50	60.50	66.50	72.50	78.50	84.50	90.50	96.50	102.50	108.50	114.50	120.50	126.50	132.50	138.50	144.50	150.50	156.50	162.50	168.50	174.50	180.50	186.50	192.50	198.50	204.50	210.50	216.50	222.50	228.50	234.50	240.50	246.50	252.50	258.50	264.50	270.50	276.50	282.50	288.50	294.50	300.50	306.50	312.50	318.50	324.50	330.50	336.50	342.50	348.50	354.50	360.50	366.50	372.50	378.50	384.50	390.50	396.50	402.50	408.50	414.50	420.50	426.50	432.50	438.50	444.50	450.50	456.50	462.50	468.50	474.50	480.50	486.50	492.50	498.50	504.50	510.50	516.50	522.50	528.50	534.50	540.50	546.50	552.50	558.50	564.50	570.50	576.50	582.50	588.50	594.50	600.50	606.50	612.50	618.50	624.50	630.50	636.50	642.50	648.50	654.50	660.50	666.50	672.50	678.50	684.50	690.50	696.50	702.50	708.50	714.50	720.50	726.50	732.50	738.50	744.50	750.50	756.50	762.50	768.50	774.50	780.50	786.50	792.50	798.50	804.50	810.50	816.50	822.50	828.50	834.50	840.50	846.50	852.50	858.50	864.50	870.50	876.50	882.50	888.50	894.50	900.50	906.50	912.50	918.50	924.50	930.50	936.50	942.50	948.50	954.50	960.50	966.50	972.50	978.50	984.50	990.50	996.50	1002.50	1008.50	1014.50	1020.50	1026.50	1032.50	1038.50	1044.50	1050.50	1056.50	1062.50	1068.50	1074.50	1080.50	1086.50	1092.50	1098.50	1104.50	1110.50	1116.50	1122.50	1128.50	1134.50	1140.50	1146.50	1152.50	1158.50	1164.50	1170.50	1176.50	1182.50	1188.50	1194.50	1200.50	1206.50	1212.50	1218.50	1224.50	1230.50	1236.50	1242.50	1248.50	1254.50	1260.50	1266.50	1272.50	1278.50	1284.50	1290.50	1296.50	1302.50	1308.50	1314.50	1320.50	1326.50	1332.50	1338.50	1344.50	1350.50	1356.50	1362.50	1368.50	1374.50	1380.50	1386.50	1392.50	1398.50	1404.50	1410.50	1416.50	1422.50	1428.50	1434.50	1440.50	1446.50	1452.50	1458.50	1464.50	1470.50	1476.50	1482.50	1488.50	1494.50	1500.50	1506.50	1512.50	1518.50	1524.50	1530.50	1536.50	1542.50	1548.50	1554.50	1560.50	1566.50	1572.50	1578.50	1584.50	1590.50	1596.50	1602.50	1608.50	1614.50	1620.50	1626.50	1632.50	1638.50	1644.50	1650.50	1656.50	1662.50	1668.50	1674.50	1680.50	1686.50	1692.50	1698.50	1704.50	1710.50	1716.50	1722.50	1728.50	1734.50	1740.50	1746.50	1752.50	1758.50	1764.50	1770.50	1776.50	1782.50	1788.50	1794.50	1800.50	1806.50	1812.50	1818.50	1824.50	1830.50	1836.50	1842.50	1848.50	1854.50	1860.50	1866.50	1872.50	1878.50	1884.50	1890.50	1896.50	1902.50	1908.50	1914.50	1920.50	1926.50	1932.50	1938.50	1944.50	1950.50	1956.50	1962.50
------	--------	------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	-------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	--------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------	---------

SPEC	Z	POLIP DATA	REF
0.00	10.00	K12 5.4	172
	120.00		180

[illegible]

60.74 = NO LOSS 60.1 = SENSITIVE - 0.64 = CR LOSS

NYT HVCNCGAPL 237A
TC= 7.00 LGS= .11

```

      PRICE = 0.00
      ACCESSION FAY:
      *RCN= 0.00

```

[illegible]

31.20 20.46 1.672 479640
(792.0)(7990)(44.1)(1356.04)

.....

CENTINE HYDROGRAPH

.....

COMBINE HYDROGRAPHS BEFORE ROUTING THROUGH B AND K LAKES EAST NO. 1 (30505)

ICOMP	IECON	ITAGE	JPLY	JPRY	INAME	ISTAGE	ISALTY
1	2	0	0	0	1	0	0
10986							

1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100
101
102
103
104
105
106
107
108
109
110
111
112
113
114
115
116
117
118
119
120
121
122
123
124
125
126
127
128
129
130
131
132
133
134
135
136
137
138
139
140
141
142
143
144
145
146
147
148
149
150
151
152
153
154
155
156
157
158
159
160
161
162
163
164
165
166
167
168
169
170
171
172
173
174
175
176
177
178
179
180
181
182
183
184
185
186
187
188
189
190
191
192
193
194
195
196
197
198
199
200
201
202
203
204
205
206
207
208
209
210
211
212
213
214
215
216
217
218
219
220
221
222
223
224
225
226
227
228
229
230
231
232
233
234
235
236
237
238
239
240
241
242
243
244
245
246
247
248
249
250
251
252
253
254
255
256
257
258
259
260
261
262
263
264
265
266
267
268
269
270
271
272
273
274
275
276
277
278
279
280
281
282
283
284
285
286
287
288
289
290
291
292
293
294
295
296
297
298
299
300
301
302
303
304
305
306
307
308
309
310
311
312
313
314
315
316
317
318
319
320
321
322
323
324
325
326
327
328
329
330
331
332
333
334
335
336
337
338
339
340
341
342
343
344
345
346
347
348
349
350
351
352
353
354
355
356
357
358
359
360
361
362
363
364
365
366
367
368
369
370
371
372
373
374
375
376
377
378
379
380
381
382
383
384
385
386
387
388
389
390
391
392
393
394
395
396
397
398
399
400
401
402
403
404
405
406
407
408
409
410
411
412
413
414
415
416
417
418
419
420
421
422
423
424
425
426
427
428
429
430
431
432
433
434
435
436
437
438
439
440
441
442
443
444
445
446
447
448
449
450
451
452
453
454
455
456
457
458
459
460
461
462
463
464
465
466
467
468
469
470
471
472
473
474
475
476
477
478
479
480
481
482
483
484
485
486
487
488
489
490
491
492
493
494
495
496
497
498
499
500
501
502
503
504
505
506
507
508
509
510
511
512
513
514
515
516
517
518
519
520
521
522
523
524
525
526
527
528
529
530
531
532
533
534
535
536
537
538
539
540
541
542
543
544
545
546
547
548
549
550
551
552
553
554
555
556
557
558
559
560
561
562
563
564
565
566
567
568
569
570
571
572
573
574
575
576
577
578
579
580
581
582
583
584
585
586
587
588
589
590
591
592
593
594
595
596
597
598
599
600
601
602
603
604
605
606
607
608
609
610
611
612
613
614
615
616
617
618
619
620
621
622
623
624
625
626
627
628
629
630
631
632
633
634
635
636
637
638
639
640
641
642
643
644
645
646
647
648
649
650
651
652
653
654
655
656
657
658
659
660
661
662
663
664
665
666
667
668
669
670
671
672
673
674
675
676
677
678
679
680
681
682
683
684
685
686
687
688
689
690
691
692
693
694
695
696
697
698
699
700
701
702
703
704
705
706
707
708
709
710
711
712
713
714
715
716
717
718
719
720
721
722
723
724
725
726
727
728
729
730
731
732
733
734
735
736
737
738
739
740
741
742
743
744
745
746
747
748
749
750
751
752
753
754
755
756
757
758
759
760
761
762
763
764
765
766
767
768
769
770
771
772
773
774
775
776
777
778
779
780
781
782
783
784
785
786
787
788
789
790
791
792
793
794
795
796
797
798
799
800
801
802
803
804
805
806
807
808
809
810
811
812
813
814
815
816
817
818
819
820
821
822
823
824
825
826
827
828
829
830
831
832
833
834
835
836
837
838
839
840
84

ROUTE COMBINED HYDROGRAPH THROUGH R AND W LAKE 74° NS.1 (3.506)

STAGE	ICOMP	IFL	ITAMP	IPOL	ISAMP	ISTAGE	IAUT
3085	1	0	0	0	0	0	0
ROUTING DATA							
1-PS	1	1	1	1	1	1	1
2-PS	1	1	1	1	1	1	1
3-PS	1	1	1	1	1	1	1
4-PS	1	1	1	1	1	1	1
5-PS	1	1	1	1	1	1	1
6-PS	1	1	1	1	1	1	1
7-PS	1	1	1	1	1	1	1
8-PS	1	1	1	1	1	1	1
9-PS	1	1	1	1	1	1	1
10-PS	1	1	1	1	1	1	1
11-PS	1	1	1	1	1	1	1
12-PS	1	1	1	1	1	1	1
13-PS	1	1	1	1	1	1	1
14-PS	1	1	1	1	1	1	1
15-PS	1	1	1	1	1	1	1
16-PS	1	1	1	1	1	1	1
17-PS	1	1	1	1	1	1	1
18-PS	1	1	1	1	1	1	1
19-PS	1	1	1	1	1	1	1
20-PS	1	1	1	1	1	1	1
21-PS	1	1	1	1	1	1	1
22-PS	1	1	1	1	1	1	1
23-PS	1	1	1	1	1	1	1
24-PS	1	1	1	1	1	1	1
25-PS	1	1	1	1	1	1	1
26-PS	1	1	1	1	1	1	1
27-PS	1	1	1	1	1	1	1
28-PS	1	1	1	1	1	1	1
29-PS	1	1	1	1	1	1	1
30-PS	1	1	1	1	1	1	1
31-PS	1	1	1	1	1	1	1
32-PS	1	1	1	1	1	1	1
33-PS	1	1	1	1	1	1	1
34-PS	1	1	1	1	1	1	1
35-PS	1	1	1	1	1	1	1
36-PS	1	1	1	1	1	1	1
37-PS	1	1	1	1	1	1	1
38-PS	1	1	1	1	1	1	1
39-PS	1	1	1	1	1	1	1
40-PS	1	1	1	1	1	1	1
41-PS	1	1	1	1	1	1	1
42-PS	1	1	1	1	1	1	1
43-PS	1	1	1	1	1	1	1
44-PS	1	1	1	1	1	1	1
45-PS	1	1	1	1	1	1	1
46-PS	1	1	1	1	1	1	1
47-PS	1	1	1	1	1	1	1
48-PS	1	1	1	1	1	1	1
49-PS	1	1	1	1	1	1	1
50-PS	1	1	1	1	1	1	1
51-PS	1	1	1	1	1	1	1
52-PS	1	1	1	1	1	1	1
53-PS	1	1	1	1	1	1	1
54-PS	1	1	1	1	1	1	1
55-PS	1	1	1	1	1	1	1
56-PS	1	1	1	1	1	1	1
57-PS	1	1	1	1	1	1	1
58-PS	1	1	1	1	1	1	1
59-PS	1	1	1	1	1	1	1
60-PS	1	1	1	1	1	1	1
61-PS	1	1	1	1	1	1	1
62-PS	1	1	1	1	1	1	1
63-PS	1	1	1	1	1	1	1
64-PS	1	1	1	1	1	1	1
65-PS	1	1	1	1	1	1	1
66-PS	1	1	1	1	1	1	1
67-PS	1	1	1	1	1	1	1
68-PS	1	1	1	1	1	1	1
69-PS	1	1	1	1	1	1	1
70-PS	1	1	1	1	1	1	1
71-PS	1	1	1	1	1	1	1
72-PS	1	1	1	1	1	1	1
73-PS	1	1	1	1	1	1	1
74-PS	1	1	1	1	1	1	1
75-PS	1	1	1	1	1	1	1
76-PS	1	1	1	1	1	1	1
77-PS	1	1	1	1	1	1	1
78-PS	1	1	1	1	1	1	1
79-PS	1	1	1	1	1	1	1
80-PS	1	1	1	1	1	1	1
81-PS	1	1	1	1	1	1	1
82-PS	1	1	1	1	1	1	1
83-PS	1	1	1	1	1	1	1
84-PS	1	1	1	1	1	1	1
85-PS	1	1	1	1	1	1	1
86-PS	1	1	1	1	1	1	1
87-PS	1	1	1	1	1	1	1
88-PS	1	1	1	1	1	1	1
89-PS	1	1	1	1	1	1	1
90-PS	1	1	1	1	1	1	1
91-PS	1	1	1	1	1	1	1
92-PS	1	1	1	1	1	1	1
93-PS	1	1	1	1	1	1	1
94-PS	1	1	1	1	1	1	1
95-PS	1	1	1	1	1	1	1
96-PS	1	1	1	1	1	1	1
97-PS	1	1	1	1	1	1	1
98-PS	1	1	1	1	1	1	1
99-PS	1	1	1	1	1	1	1
100-PS	1	1	1	1	1	1	1

PEAK OUTFLOW IS 80% AT TIME 16.47 HOURS
 PEAK OUTFLOW IS 80% AT TIME 16.25 HOURS
 PEAK OUTFLOW IS 11% AT TIME 16.00 HOURS
 PEAK OUTFLOW IS 130% AT TIME 16.17 HOURS
 PEAK OUTFLOW IS 16% AT TIME 16.00 HOURS
 PEAK OUTFLOW IS 192% AT TIME 16.00 HOURS
 PEAK OUTFLOW IS 213% AT TIME 16.00 HOURS
 PEAK OUTFLOW IS 234% AT TIME 16.00 HOURS
 PEAK OUTFLOW IS 16.959% AT TIME 16.00 HOURS

COMPARISON OF DAM SAFETY ANALYSIS

PLAN 1	ELEVATION STATION OUTFLOW	INITIAL VALU STRESS ACFT	OUTFLAV CRESS STRESS ACFT	TOP OF DAM STRESS ACFT	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
RATIO OF PPE	MAXIMUM RESERVATION WEATHER	MAXIMUM STRESS ACFT	MAXIMUM OUTFLAV STRESS ACFT	MAXIMUM OUTFLAV STRESS ACFT	MAXIMUM OUTFLAV STRESS ACFT	MAXIMUM OUTFLAV STRESS ACFT	MAXIMUM OUTFLAV STRESS ACFT
.15	955.00	0.00	43	24	0.00	15.00	0.00
.17	955.00	0.00	43	27	0.00	15.00	0.00
.18	955.00	0.00	43	30	0.00	15.00	0.00
.19	955.00	0.00	43	33	0.00	15.00	0.00
.20	955.00	0.00	43	36	0.00	15.00	0.00
.21	955.00	0.00	43	39	0.00	15.00	0.00
.22	955.00	0.00	43	42	0.00	15.00	0.00
.23	955.00	0.00	43	45	0.00	15.00	0.00

SUMMARY OF DAM SAFETY ANALYSIS

ELEVATION STAGE OUTFLOW	INITIAL VALUE 95% 75% 50%	SETBACK CRIST 95% 75% 50%	TOP OF DAM HFT.25 100% 125%	MAXIMUM DEPTH OVER DAM	MAXIMUM STRESS 40-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
RATED OF PVE									
41.0	432.00	0.00	10.0	10.0	10.0	10.0	0.10	16.67	0.00
41.5	472.17	0.00	10.0	10.0	10.0	10.0	0.10	16.67	0.00
41.7	472.12	0.00	10.0	10.0	10.0	10.0	0.10	16.67	0.00
41.8	472.06	0.00	10.0	10.0	10.0	10.0	0.10	16.67	0.00
41.9	472.00	0.00	10.0	10.0	10.0	10.0	0.10	16.67	0.00
42.0	472.00	0.00	10.0	10.0	10.0	10.0	0.10	16.67	0.00
42.1	472.00	0.00	10.0	10.0	10.0	10.0	0.10	16.67	0.00
42.2	472.00	0.00	10.0	10.0	10.0	10.0	0.10	16.67	0.00
42.3	472.00	0.00	10.0	10.0	10.0	10.0	0.10	16.67	0.00
42.4	472.00	0.00	10.0	10.0	10.0	10.0	0.10	16.67	0.00
42.5	472.00	0.00	10.0	10.0	10.0	10.0	0.10	16.67	0.00

DATE
FILMED
- 8